

Double J stent removed 6 weeks after a kidney transplant.
Note the encrustation at the bladder end of the stent. It is likely that other calcific debris was left in the renal pelvis and ureter when the stent was removed.

